
Order #XXXXX MOD-1353 iPad Kiosk

Item	Qty.	Description
1	1	Base Plate
2	1	10" Z72 Horizontal Extrusior
_		—



Steps:

- 1) Slide Infill into stand verticals as shown.
- 2) Attach horizontal [2] between stand verticals.
- 3) Attach base plate [1] to stand verticals, using bolts.
- 4) Attach mount plate [3] to stand, using bolt

NOTE: Mount Plate must rotate to left and right before installing Clamshell.

- 5) Attach clamshell to mount plate [3], using hex nuts.
- 6) Insert iPad into clamshell then route cords. See Cord Management for iPad detail.
- 7) Attach literature holders to stand. See Literature Holder Attachment detail.


Cord Management Cord management Tond management Route cord through conduit. Attach conduit by pinching the opening and inserting into the groove of stand.

Optional Cover for Home Button




- 1) Remove foam lining from inside bottom of clamshell.
- 2) Attach Home Button Shield with double-sided tape to inside of clamshell, keeping top of shield flush with clamshell opening.

NOTE: This is a permanent fix and can't be easily removed.



Completed Assembly

* Literature Holder Attachment




connector to post. Tighten

locks to secure.

Clamshell iPad Cord Access

Cord Management for iPad



SETUP INSTRUCTIONS

General Setup Instructions


- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.




- For Cleaning Metal, Plex, & Laminate Parts: Use a MILD NON-ABRASIVE cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure. Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials. All provided packing materials are for ease of repacking & component protection.

Disassembly

- For loss prevention, tighten all setscrews and locks during disassembly




Hex Tool - Essential for Assembly



Part Identification - Numbering




MARNING





Spline Connection

Extrusion & Lock Connection



Base Plate & Extrusion Connection





Engaged Lock



DO NOT USE POWER TOOLS



LADDERS OR LIFTS MAY BE REQUIRED



ALL CONNECTIONS MUST BE TIGHTLY SECURED