


## Steps:


- Connect lighting power cords and attach transformer.
  See Light to Light Connection & Light to Transformer Connection details.
- 2) Attach graphic to front of couner, using standoffs and caps. See Graphic Attachment detail.





Completed Assembly







Side View of Crate Interior